



**RENAULT Grand Scenic: 1EWC158**

|                         |                          |              |  |
|-------------------------|--------------------------|--------------|--|
| Vinnnumber:             | <b>VF1JZ14A648709698</b> | Versionname: | <b>GR.SCENIC Energ.Bose Edit.5pl.FAP 110PK</b> |
| First Registrationdate: | <b>4/04/2013</b>         | Fiscalpower: |  |
| Expertise Mileage:      | <b>101893</b>            | Power Kw:    | <b>81</b>                                      |
| Bodytype:               | <b>Hatchback</b>         | Body color:  | <b>Burgundy</b>                                |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                 |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                               |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                      |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2111</b>                                    |
| Number of doors:        | <b>5</b>                 |              |  |
| Number of seats:        | <b>5</b>                 |              |  |
| Number head rests:      | <b>5</b>                 |              |  |
| Rims summer:            | <b>Aluminium</b>         |              |  |
| Category:               | <b>Passenger Car</b>     |              |  |
| Oil level:              | <b>OK</b>                |              |  |

**Options**

|                                |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Central consol F                      |
| Windows electric F             | Luggage cover                         |
| Windows electric R             | Front parking sensors                 |
| Cruise Control                 | Rear parking sensors                  |
| Steering wheel multifunctional | Type of Tow bar                       |
| Radio multimedia               | <b>Tow bar fixed</b>                  |
| Type of headlighting           | <b>Headlighting Halogen</b>           |
| Type of GPS                    | <b>GPS big screen color</b>           |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/91 V LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

**Assistance equipment**

|   |         |
|---|---------|
| Total cost ex VAT   | 1756,35 |
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80  |



|   |        |
|---|--------|
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|--------|



|  |      |
|--|------|
| Alloy rim R R polished, Rust, Acceptable | 0,00 |
|--|------|

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Alloy rim F R polished, Rust, Acceptable 0,00

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting 63,00



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50

