



VOLKSWAGEN Passat: 1CMG513

Vinnnumber:	WVWZZZ3CZCE077131	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	3/01/2012	Fiscalpower:	
Expertise Mileage:	83760	Power Kw:	77
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1108
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	866,95
-------------------	---------------

Door F R, Bad repair, Paint	0,00
-----------------------------	-------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Hail damage, PDR - Hail 125,00




Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Stone chip(s), Paint 0,00



Rear window, Scratch(es), E - Replace 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bad repair, Paint 0,00



Bonnet, Bad repair, Paint 0,00

