


RENAULT Kangoo: 1HGF142

Vinnnumber:	VF1KWX8B551320394	Versionname:	KANGOO Energy eXTrem
First Registrationdate:	14/07/2014	Fiscalpower:	90PK
Expertise Mileage:	201716	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1509
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

 Total cost ex VAT 1376,60


 Bodywork, Not original part, Acceptable 0,00
No pictures to display

 Bumper R, Damaged, E - Replace 329,40

 Alloy rim F R, Scratch(es), Acceptable 0,00
No pictures to display

 Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 232,88

 Luggage space cover, Missing, E - Replace 80,00

		<p>Luggage space cover, missing, E - Replace</p> <p>80,00</p>
<p>Rearview mirror housing R, Damaged, E - Replace</p>		<p>84,00</p>
		<p>Front bumper, Scratch(es), Acceptable</p> <p>0,00</p> <p>No pictures to display</p>
<p>Bonnet, Bump(s), LI - Repair and paint (complete)</p>		<p>217,56</p>
		<p>Alloy rim R R, Scratch(es), Acceptable</p> <p>0,00</p> <p>No pictures to display</p>
<p>Front bumper, Incomplete, E - Replace</p>		<p>44,00</p>
		<p>Wing F R, Scratch(es), Acceptable</p> <p>0,00</p> <p>No pictures to display</p>
<p>Tailgate, Bump(s), Acceptable</p>		<p>0,00</p> <p>No pictures to display</p>
<p>Ignition key, Missing, E - Replace</p>		<p>150,00</p> <p>No pictures to display</p>
<p>Rearview mirror L complete, Scratch(es), Acceptable</p>		<p>0,00</p> <p>No pictures to display</p>
<p>Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)</p>		<p>238,76</p>
		