




<b>RENAULT Master 35 L3H1: 1FFV485</b>			
Vinnnumber:	<b>VF1MAF4FE49125760</b>	Versionname:	<b>MASTER 35 B/F L3H2 Gr.Conf.(E5)150PK</b>
First Registrationdate:	<b>18/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>164802</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV17</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

















<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>			
Winter tyres:	<b>225/65/16/112 R Steel</b>		
	Fr.L.	Fr.R.	Michelin: 8 mm
	Re.L.	Re.R.	Michelin: 9 mm

<b>Assistance equipment</b>	
Total cost ex VAT	1105,75
Trunk door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	231,15



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------

			Bonnet, Chemical pollution, LI - Repair and paint (complete)	217,56
			Wing trim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Wing F R, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Door R R, Bump(s), PDR - Knock out without painting				102,60
				
				
Door F L, Bump(s), PDR - Knock out without painting				82,80
				
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)				232,88
				
Bodywork, Not original part, Acceptable				0,00
<i>No pictures to display</i>				