



## VOLVO V50: 1DGE434

Vinnnumber:	<b>YV1MW84F1C2697534</b>	Versionname:	<b>V50 BRE DRIVe</b>	Start/Stop	<b>99g 115PK</b>
First Registrationdate:	<b>9/05/2012</b>	Fiscalpower:			
Expertise Mileage:	<b>168817</b>	Power Kw:		<b>84</b>	
Bodytype:	<b>Break</b>	Body color		<b>Grey</b>	
Gearbox:	<b>MAN 6 VIT</b>	Paint type		<b>Metalic</b>	
Transmission:	<b>Front</b>	Rims summer		<b>Aluminium</b>	
Fueltype:	<b>Diesel</b>	Oil level		<b>OK</b>	
Battery functioning	<b>Yes</b>	Parking lot		<b>2811</b>	
Number of doors	<b>5</b>				
Number of seats	<b>5</b>				
Number head rests	<b>5</b>				
Rims summer	<b>Aluminium</b>				
Category	<b>Passenger Car</b>				
Oil level	<b>OK</b>				

## Options

Radio CD	Sun Roof electric	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>190,00</b>
-------------------	---------------

Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*


Rear spoiler, Bad repair, Paint	<b>0,00</b>
---------------------------------	-------------




Sill outer R, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear window, Scratch(es), Acceptable 0,00

*No pictures to display*

Seat cover F L, Worn, Acceptable 0,00

