



VOLVO XC60: 1ECM476			
Vinnumber:	YV1DZ31A1D2404854	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	19/10/2012	Fiscalpower:	
Expertise Mileage:	94301	Power Kw:	100
Bodytype:	SUV	Body color:	Light Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2324
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 0,5 mm	Re.R.	Pirelli: 7,5 mm


Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			640,32
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16



Door panel F L, Hole, E - Replace	132,00
-----------------------------------	---------------



Ceiling, Dirty, Acceptable	0,00
----------------------------	-------------



Centre console, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), E - Replace 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

