



VOLKSWAGEN Touran: 1HAN853			
Vinnnumber:	WVGZZZ1TZEW089936	Versionname:	TOURAN Highline BMT St&St 7pl.140PK
First Registrationdate:	4/06/2014	Fiscalpower:	
Expertise Mileage:	82164	Power Kw:	103
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2327
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining Alcantara
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Fr.R.	Michelin: 7 mm
	Re.L.	Re.R.	Michelin: 4 mm

Assistance equipment	
Total cost ex VAT	1233,99
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20




Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

