



SEAT Alhambra: 1EOA021

Vinnnumber:	VSSZZZ7NZDV512577	Versionname:	ALHAMBRA Ecom.Style
First Registrationdate:	4/02/2013	Fiscalpower:	DPF 136PK
Expertise Mileage:	114036	Power Kw:	100
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3324
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 8 mm	Re.R.	Semperit: 8 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1218,13
Door F L, Bad repair, Paint			0,00



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

no pictures to display

Rearlight L, Crack, E - Replace 132,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Bad repair, Paint 0,00



Tyre repair kit, Missing, E - Replace 252,64



Wing R L, Chemical polution, LI - Repair and paint (complete) 369,84



Rearview mirror housing L, Chemical polution, LI - Repair and paint (complete) 115,56



Front bumper, Bad repair, Paint 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Wing F L, Bump(s), Acceptable 0,00

No pictures to display