



VOLVO V60: 1HDG335

Vinnnumber:	YV1FW31A1F1218966	Versionname:	V60 BRE D3 Kinetic 136PK
First Registrationdate:	24/06/2014	Fiscalpower:	
Expertise Mileage:	162967	Power Kw:	100
Bodytype:	Break	Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1702
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/40/18/95 V LightMetal			
Winter tyres:	Fr.L.	Kleber: 8 mm	Fr.R.	Kleber: 8 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	607,44
-------------------	--------

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper R, Bump(s) and scratch(es), Smart repair 110,64



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

