



VOLKSWAGEN Passat: 1GAI339

Vinnnumber:	WVWZZ3CZEE081973	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	5/12/2013	Fiscalpower:	
Expertise Mileage:	120930	Power Kw:	77
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 24100KM 657D	Parking lot:	2724
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage		Sun Roof electric
GPS storage	HD	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1540,15
-------------------	----------------


Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
-------------------------------------------------------------	---------------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---------------------------------------------------------	---------------



Bonnet, Hail damage, PDR - Knock out without painting 181,80



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display




Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bad repair, Acceptable 0,00

