


RENAULT Koleos: RM9886

Vinnnumber:	VF1VY5VGNUC495868	Versionname:	KOLEOS PH.3 4x4 Intens 150PK
First Registrationdate:	6/02/2014	Fiscalpower:	
Expertise Mileage:	126421	Power Kw:	110
Bodytype:	SUV	Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3433
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Sun Roof electric
Windows electric R	Panoramic roof
Cruise Control	Central consol F
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/18/98 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	665,03
-------------------	--------

Wing F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Scratch(es), It - Spot repair	115,56
---	--------



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

115,56



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door R L, Scratch(es), It - Spot repair	115,56
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display