



VOLKSWAGEN Golf: 1EXB121			
Vinnnumber:	WVWZZZAUZDW127009	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	11/04/2013	Fiscalpower:	
Expertise Mileage:	140274	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2325
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear				
	195/65/15/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			95,00
Door panel F L, Scratch(es), Acceptable			0,00



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------





Tailgate, Rust, Acceptable

0,00



Wing R R, Bump(s), Acceptable

0,00



Door R R, Bump(s), Acceptable

0,00



Wing R L, Bump(s), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Front bumper, Scratch(es), Acceptable

0,00



Interior, Stain, Cleaning

0,00

