



AUDI A4: 1GER430

| | | | |
|------------------------------------|-------------------------|--------------|--|
| Vinnumber: | WAUZZ8K2EA082433 | Versionname: | A4 AVANT TDi Multitr.136PK Aut. |
| First Registrationdate: | 17/01/2014 | Fiscalpower: | |
| Expertise Mileage: | 199567 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Beige |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1627 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 225/55/16/95 H LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

Total cost ex VAT 1535,39

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18




Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door R L, Bump(s), PDR - Knock out without painting 63,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

