


**BMW 116 eD: 1ET0026**

Vinnnumber:	<b>WBA1C91010J508628</b>	Versionname:	<b>1 HATCH 116d Eff.Dyn.Ed. 116PK</b>
First Registrationdate:	<b>18/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>82761</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>		
Maintenance	<b>IN 10000KM</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS portable</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	
Level control		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	24,00
-------------------	-------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Sill trim R, Scratch(es), Acceptable	0,00
--------------------------------------	------



Wheel cover F R, Scratch(es), E - Replace 24,00



Front bumper, Stone chip(s), Acceptable 0,00



Wing R R, Bump(s) and scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00

