


BMW 1: 1GQF433

Vinnnumber:	WBA1C910X0J523094	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	140779	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 190 KM	Parking lot:	4628
Maintenance:	OK		
Maintenance:	4/04/2019		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

 Total cost ex VAT 707,50

 Wing R R, Bad repair, P - Check 0,00

 Rear window, Scratch(es), Acceptable 0,00

No pictures to display

 Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Hail damage, PDR - Hail 100,00




Maintenance, Maintenance, Acceptable 0,00



Door R R, Bad repair, P - Check 0,00



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Door R R, Bump(s), PDR - Knock out without painting 63,00



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bad repair, P - Check 0,00

