


**BMW 3: 1EUE169**

Vinnnumber:	<b>WBA3K31070F744924</b>	Versionname:	<b>3 TOURING 320d 163PK</b>
First Registrationdate:	<b>21/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>102454</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Anthracite</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>327,36</b>
-------------------	---------------

Wing R R, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------





Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

*No pictures to display*

Door F R, Bump(s) and scratch(es), It - Spot repair	115,56
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*