



BMW 520: 1FLM975			
Vinnumber:	WBA5J31000D070283	Versionname:	D
First Registrationdate:	7/08/2013	Fiscalpower:	
Expertise Mileage:	159315	Power Kw:	135
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3203
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
GPS storage HD	Seats electric F R
GPS storage	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting Headlighting Xenon	
Type of GPS GPS big screen color	
Type of Lining Lining leather	
Type of climate control Autom climate control	
Head-up Display	
Level control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	245/45/18/100 V LightMetal			
	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
Runflat	Yes
Total cost ex VAT	1696,92
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	350,16





Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Worn, Acceptable 0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bodywork, Damaged, Acceptable 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Air vent R M, Broken, E - Replace 158,40



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Floor covering F L, Burned, Smart repair

64,32



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

