


FORD S Max: 1EWM268

Vinnnumber:	WF0SXXGBWSDJ85181	Versionname:	S-MAX Titanium DPF
First Registrationdate:	8/04/2013	Fiscalpower:	136PK
Expertise Mileage:	164567	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3108
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2194,99
-------------------	---------

Outer door handle R R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ashtray R, Unclasp(ed), N - Mount/Dismount	12,00
--	-------



Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Rearlight R tailgate, Crack, E - Replace	87,00
--	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Trunk lid covering R, Damaged, E - Replace	62,00
--	-------



Protection plate M, Tear, E - Replace	62,00
---------------------------------------	-------



Rearview mirror L complete, Crack, E - Replace	192,00
--	--------



Door R R, Bump(s), LI - Repair and paint (complete)	382,02
---	--------



Seat cover F L, Damaged, Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Windscreen, Stone chip(s), E - Replace	0,00
--	------



Door F L, Scratch(es), LI - Repair and paint (complete)

382,02

