


MERCEDES B: 1EPR434

Vinnumber:	WDD2462001J146719	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	18/02/2013	Fiscalpower:	
Expertise Mileage:	71728	Power Kw:	80
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1507
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

 Total cost ex VAT 2501,18

 Wheel cover F R, Scratch(es), E - Replace 30,00


Roof pillar R, Chemical pollution, LI - Repair and paint (complete)

220,18



Door F R, Chemical polution, LI - Repair and paint (complete) 318,35



Rearview mirror housing L, Chemical polution, LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Tailgate, Chemical polution, LI - Repair and paint (complete) 301,68



Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Door R R, Chemical polution, LI - Repair and paint (complete) 318,35



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Chemical polution, LI - Repair and paint (complete) 115,56



Windscreen, Stone chip(s), Acceptable 0,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Interior, Dirty, Cleaning

50,00



Wheel cover R R, Scratch(es), E - Replace

30,00

