



JAGUAR XF: 1GRW273

Vinnnumber:	SAJAA0224ENU32506	Versionname:	XF SPORTBRAKE V6 S
First Registrationdate:	11/04/2014	Fiscalpower:	275PK Aut.
Expertise Mileage:	112089	Power Kw:	202
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3128
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 3,5 mm	Re.R.	Michelin: 3,5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1556,58
Backrest cover R M, Deformed, P - Check			0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), Acceptable 0,00

No pictures to display

Door frame R R, Bump(s) and scratch(es), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Door frame F L, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00





Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), P - Check 0,00

