


FORD Mondeo: 1EJT784

Vinnnumber:	WFOGXGGBGCL66804	Versionname:	MONDEO CLIP Titanium
First Registrationdate:	2/01/2013	Fiscalpower:	136PK
Expertise Mileage:	113799	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3204
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	289,20
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), It - Spot repair	115,56



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Door seal R L, Worn, P - Check	0,00
--------------------------------	------

No pictures to display

Internal Boot Lining R, Scratch(es), Smart repair	110,64
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display