



FORD Mondeo: 1FDU775

Vinnumber:	WFOGXGBBGDP14780	Versionname:	DIESEL
First Registrationdate:	3/06/2013	Fiscalpower:	
Expertise Mileage:	182640	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	A ETE FAIT A 80000KM BON POUR 18000KM	Parking lot:	3115
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Uniroyal: 6,5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	886,99
--------------------------	---------------

Wing R R, Bump(s), PDR - Knock out without painting	63,00
--	--------------



Ceiling, Tear, E - Replace	494,00
-----------------------------------	---------------



Bonnet, Scratch(es), 67 - Polish 55,19



Wing R L, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Bad repair, LI - Repair and paint (complete) 211,80

