


MERCEDES CLA: 1HJH399

Vinnumber:	WDD1173121N119600	Versionname:	CLA BER 180 CDI 109PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	76281	Power Kw:	80
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3522
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1050,15
-------------------	---------

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door F R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Roof pillar L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display