



**FORD Grand C-Max: 1FDU737**

Vinnnumber:	<b>WF0HXWPBHDP33660</b>	Versionname:	<b>GR.C-MAX Titanium St/St</b>
First Registrationdate:	<b>3/06/2013</b>	Fiscalpower:	<b>95PK</b>
Expertise Mileage:	<b>161661</b>	Power Kw:	<b>70</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2632</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Seats electric F L	
Windows electric F	Central consol F	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 2 mm</b>	Fr.R.	<b>Uniroyal: 2 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

**Assistance equipment**

Total cost ex VAT	886,80
Wing R R, Scratch(es), LI - Repair and paint (complete)	0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door frame R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Luggage space cover, Missing, E - Replace 240,00

