



FORD TRANSIT : 1DWM590

Vinnumber:	WF05XXBDF5CD43941	Versionname:	
First Registrationdate:	18/09/2012	Fiscalpower:	
Expertise Mileage:	217259	Power Kw:	
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2522
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Rear parking sensors
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/70/15/104 R LightMetal			
Winter tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1386,52
-------------------	---------

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper F L, Crack, E - Replace	580,00
--------------------------------	--------



Rearlight L, Crack, E - Replace	91,50
---------------------------------	-------



Rearview mirror R complete, Missing, E - Replace 138,00



Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Roof, Stone chip(s), Acceptable 0,00



Wheel cover R R, Missing, E - Replace 22,50



Reversible boot mat, Dirty, Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover F R, Missing, E - Replace 22,50



Wing R L, Bump(s), Acceptable 0,00

No pictures to display