



SKODA Superb: 1EUE137

Vinnnumber:	TMBJJ73TXD9046503	Versionname:	SUPERB COMBI GreenLine
First Registrationdate:	21/03/2013	Fiscalpower:	Active DPF 105PK
Expertise Mileage:	114293	Power Kw:	77
Bodytype:	Break	Body color:	Beige
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1305
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1320,09
-------------------	----------------

Rearlight L, Scratch(es), E - Replace	132,00
---------------------------------------	---------------




Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	---------------



Wheel cover F L, Scratch(es), E - Replace	36,00
---	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wheel cover F R, Scratch(es), E - Replace	36,00
---	-------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	36,00
---	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), E - Replace	36,00
---	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	441,84
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display