



RENAULT Scenic: 1ELF439

Vinnnumber:	VF1JZ140648184134	Versionname:	SCENIC Energ.Expression
First Registrationdate:	11/01/2013	Fiscalpower:	110PK
Expertise Mileage:	143824	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3812
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
GPS storage	
GPS storage	SD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/98 V Steel			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1265,14
-------------------	---------

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F R, Stain, Forfeit	12,00
--------------------------------	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	356,20
---	--------



Bumper corner R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wheel cover F R, Damaged, E - Replace	30,00
---------------------------------------	-------



Seat cover R L, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Sill outer L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display