



RENAULT Master 35 L2H2: 1CHF135

Vinnnumber:	VF1MAFEEC46053899	Versionname:	MASTER 35 B/F L2H2 Gr.Conf.145PK
First Registrationdate:	25/11/2011	Fiscalpower:	
Expertise Mileage:	138369	Power Kw:	107
Bodytype:	Transporter	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV003
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/108 R Steel			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1437,02
-------------------	----------------

Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	217,56
---	---------------



Sliding door R, Bump(s), LI - Repair and paint (complete)	382,02
---	---------------





Rearview mirror L complete, Damaged, E - Replace 138,00



Roof pillar L, Bump(s), LI - Repair and paint (complete) 237,14



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Seat cover F L, Worn, Acceptable 0,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15

