



OPEL Astra: 1EFV014

Vinnnumber:	W0LPD8EA1D8019097	Versionname:	ASTRA BRE ecoFLEX Enjoy St/St 95PK
First Registrationdate:	20/11/2012	Fiscalpower:	
Expertise Mileage:	152313	Power Kw:	70
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2629
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/98 MS Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	3026,34
-------------------	---------

Trunk lid covering R, Damaged, E - Replace	62,00
--	-------



Windscreen, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Boot carpet, Damaged, E - Replace	25,00
-----------------------------------	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Bumper R, Damaged, Le - Replace and paint	651,00
---	--------



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	358,50
---	--------



Dashboard, Hole, Smart repair	110,64
-------------------------------	--------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door panel R R, Damaged, Smart repair 110,64



Tailgate, Bump(s), LI - Repair and paint (complete) 301,68

