


OPEL Astra: 1FSE191

Vinnnumber:	WOLPD8EA8E8010544	Versionname:	ASTRA BRE ecoFL.Enjoy Active St/St 95PK
First Registrationdate:	8/10/2013	Fiscalpower:	
Expertise Mileage:	188342	Power Kw:	70
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2710
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/98 MS Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	245,80
-------------------	---------------

Instrument panel cover, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	235,80
---	---------------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Reflector, Damaged, E - Replace

10,00



Rear window, Scratch(es), Acceptable

0,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display