


MERCEDES A: 1GDL827

Vinnnumber:	WDD1760121J232980	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	8/01/2014	Fiscalpower:	
Expertise Mileage:	112886	Power Kw:	80
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1232
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
Windows electric F		Luggage cover
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	211,80
-------------------	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Repaired, Acceptable	0,00
--------------------------------	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display