



PEUGEOT 308: 1ENW829			
Vinnnumber:	VF34E9HP0CS275515	Versionname:	308 SW Access 92PK
First Registrationdate:	4/02/2013	Fiscalpower:	
Expertise Mileage:	139634	Power Kw:	68
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options		
Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT		899,94	
Bumper R, Bump(s), LI - Repair and paint (complete)		211,80	





Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	-------



Bonnet, Bad repair, Paint	0,00
---------------------------	------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Wheel cover R R, Damaged, E - Replace	30,00
---------------------------------------	-------



Rearlight R, Scratch(es), E - Replace	114,00
---------------------------------------	--------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Bumper R, Bump(s), Smart repair	110,64
---------------------------------	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------

