



SKODA Octavia: 1GPI405

Vinnumber:	TMBJG7NE0E0179791	Versionname:	COMBI GreenLine Ambition 110PK
First Registrationdate:	25/03/2014	Fiscalpower:	
Expertise Mileage:	177499	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1606
Maintenance:	OVER 3400 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
TV/DVD screen F	Luggage cover
GPS storage	Front parking sensors
GPS storage	Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	Tow bar removable
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1259,00
-------------------	---------

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Seat cover R, Stain, Cleaning 50,00



Windscreen, Stone chip(s), E - Replace 487,20



Bumper R, Scratch(es), Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00



Seat cover F L, Tear, E - Replace 360,00



Maintenance, Maintenance, P - Check 0,00

