



**OPEL Insignia: 1HFJ537**

Vinnnumber:	<b>WOLGT8ES4E1139305</b>	Versionname:	<b>INSIGNIA BRE ecoFLEX Cosmo 140PK</b>
First Registrationdate:	<b>8/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>140688</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1331</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage	<b>HD</b>	Sun Roof electric
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>245/45/18/100 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 2 mm</b>	Fr.R.	<b>Pirelli: 2 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>684,80</b>
-------------------	---------------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------





Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Foglight R, Broken, E - Replace 138,00



Door R R, Scratch(es), Acceptable 0,00



Bumper moulding F R, Broken, E - Replace 50,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

