



**RENAULT Scenic: 1GJD997**

Vinnnumber:	<b>VF1JZ14K650186522</b>	Versionname:	<b>SCENIC Energy Life 110PK</b>
First Registrationdate:	<b>21/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>87308</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1405</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
Windows electric F		Luggage cover
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/92 H Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 1 mm</b>	Fr.R.	<b>Michelin: 1 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1531,62</b>
--------------------------	----------------

<b>Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>301,68</b>
--	---------------



<b>Front bumper, Scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>
--	---------------



Bonnet, Chemical polition, LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), It - Spot repair 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), E - Replace 272,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Wheel cover F R, Missing, E - Replace 30,00

