



RENAULT Grand Espace: 1ERM150

Vinnumber:	VF1JKFHC648442644	Versionname:	GR.ESPACE Business 130PK
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	159818	Power Kw:	96
Bodytype:	MPV	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1215
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Panoramic roof
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1803,54
-------------------	----------------

Internal Boot Lining R, Damaged, Smart repair	110,64
---	---------------



Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
---	---------------



Backrest cover R L, Scratch(es), Smart repair	64,32
---	--------------



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover R R, Scratch(es), Smart repair 64,32



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Internal Boot Lining L, Damaged, Smart repair 110,64



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84

