


OPEL Insignia: 1EWM336

Vinnumber:	WOLGT6EL9D1087262	Versionname:	INSIGNIA BER ecofl.Cosmo S/S DPF 130PK
First Registrationdate:	8/04/2013	Fiscalpower:	
Expertise Mileage:	200802	Power Kw:	96
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Luggage cover
GPS storage	SD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	368,80
-------------------	--------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Interior, Dirty, Cleaning	25,00
---------------------------	-------





Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Engine protective plate, Hole, E - Replace	0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Tyre F R, Damaged, E - Replace	132,00
--------------------------------	--------



Seat cover F L, Damaged, Acceptable	0,00
-------------------------------------	------

