



OPEL Astra: 1CDU128

Vinnnumber:	WOLPD8EA9C8014180	Versionname:	ASTRA BRE ecoFLEX Enjoy FAP 95PK
First Registrationdate:	27/10/2011	Fiscalpower:	
Expertise Mileage:	165664	Power Kw:	70
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3426
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1057,62
Wheel cover F R, Scratch(es), E - Replace	30,00



Front bumper, Bad repair, Paint	0,00
--	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------



Bodywork, Not original part, Acceptable 0,00

No pictures to display


Wing R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Damaged, Smart repair 110,64



Tailgate, Bump(s), LI - Repair and paint (complete) 301,68



Sill outer R, Bump(s), LI - Repair and paint (complete) 310,50



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Wheel cover R L, Scratch(es), E - Replace 30,00

