



**VOLKSWAGEN Polo: 1HZC288**

Vinnnumber:	<b>WVWZZZ6RZFY168056</b>	Versionname:	<b>POLO Comfortline BMT</b>
First Registrationdate:	<b>4/11/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>58538</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1311</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/60/15/84 H Steel</b>			
Summer tyres:	Fr.L.	<b>Hankook: 3 mm</b>	Fr.R.	<b>Hankook: 3 mm</b>
	Re.L.	<b>Hankook: 6 mm</b>	Re.R.	<b>Hankook: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>476,68</b>
-------------------	---------------

Wheel cover F L, Missing, E - Replace	<b>24,00</b>
---------------------------------------	--------------



Wing F L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Bumper F L, Scratch(es), Acceptable	<b>0,00</b>
-------------------------------------	-------------

*No pictures to display*

Wheel cover R L, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bodywork, Not original part, Acceptable	0,00
---	------

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace	24,00
---	-------



Door F R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

*No pictures to display*