



VOLKSWAGEN Polo: 1HZC291

Vinnnumber:	WVWZZZ6RZFY173664	Versionname:	POLO Comfortline BMT
First Registrationdate:	4/11/2014	Fiscalpower:	75PK
Expertise Mileage:	122174	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1609
Maintenance:	14900KM OF 252 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	601,44
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Glove compartment lid, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Missing, E - Replace	24,00



Door F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Missing, E - Replace	24,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Front bumper, Damaged, LI - Repair and paint (complete) 217,44



Rear window, Not original part, P - Check 0,00



Door frame F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F R, Damaged, E - Replace 312,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display