



**SKODA Superb: 1EWR381**

Vinnumber:	<b>TMBJJ93T4D9045309</b>	Versionname:	<b>SUPERB COMBI Ambition DPF 105PK</b>
First Registrationdate:	<b>9/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>102174</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3720</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Panoramic roof
Steering wheel multifunctional	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	<b>Headlighting Halogen</b>
Type of Lining	<b>GPS big screen color</b>
Type of climate control	<b>Lining leather</b>
	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/94 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------


Total cost ex VAT	1831,72
-------------------	---------

Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------





Rearlight L, Damaged, E - Replace 124,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F, Broken, E - Replace 17,28




Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Reflector, Damaged, E - Replace 10,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Door F L, Bump(s), PDR - Knock out without painting 82,80

