



VOLVO V40: 1NBC576			
Vinnnumber:	<b>YV1MV74L1G2321107</b>	Versionname:	<b>2.0 D2 KINETIC</b>
First Registrationdate:	<b>8/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>76083</b>	Power Kw:	<b>88</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1709</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>


Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>285,00</b>
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>
--	--	--	--------------



			<b>95,00</b>
--	--	--	--------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s), Acceptable 0,00

*No pictures to display*

Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R L, Scratch(es), Acceptable 0,00

*No pictures to display*