



| VOLVO V60: 1EOE297 | | | |
|-------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber: | YV1FW84A1D1126776 | Versionname: | V60 D2 Kinetic St/St 115PK |
| First Registrationdate: | 5/02/2013 | Fiscalpower: | |
| Expertise Mileage: | 115748 | Power Kw: | 84 |
| Bodytype: | | Body color: | Beige |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3110 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | CD |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres: | 235/45/17/94 H LightMetal | | | |
| | Fr.L. | Semperit: 4 mm | Fr.R. | Semperit: 4 mm |
| | Re.L. | Semperit: 4 mm | Re.R. | Semperit: 4 mm |

| Assistance equipment | | | |
|--|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 671,50 |
| Alloy rim F L, Scratch(es), Acceptable | | | 0,00 |



| | | | |
|-----------------------------------|--|--|-------------|
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
|-----------------------------------|--|--|-------------|




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Windscreen, Repaired, P - Check 0,00

