


MERCEDES C: 1JNG655

Vinnnumber:	WDD2052371F155778	Versionname:	C BRE 200 BlueTEC 136PK
First Registrationdate:	23/01/2015	Fiscalpower:	
Expertise Mileage:	160857	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2633
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 0,1 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1149,80
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Boot carpet, Damaged, E - Replace	100,00
-----------------------------------	---------------



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Outer backrest protection R, Damaged, E - Replace 149,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Tyre F R, Worn, Acceptable 0,00



Outer backrest protection L, Damaged, E - Replace 149,00




Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 150,00





Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Luggage space cover, Missing, E - Replace	240,00

