


MERCEDES B: 1HGF132

Vinnumber:	WDD2462121J277314	Versionname:	B 180CDI BE Edition 109PK
First Registrationdate:	14/07/2014	Fiscalpower:	
Expertise Mileage:	178454	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1330
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			220,18
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rocker panel inner R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Scratch(es), LI - Repair and paint (complete)			220,18



Door R L, Scratch(es), Acceptable

0,00

No pictures to display