


**NISSAN QASHQAI: 1KDZ054**

Vinnumber:	<b>SJNFAAJ11U1291341</b>	Versionname:	<b>1.5 DCI CONNECT EDITION</b>
First Registrationdate:	<b>10/04/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>141244</b>	Power Kw:	<b>81</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3831</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Panoramic roof
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/18/99 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 2 mm</b>	Fr.R.	<b>Continental: 2 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>727,28</b>
-------------------	---------------

Engine protective plate, Hole, E - Replace	<b>72,00</b>
--	--------------



Door R L, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

*No pictures to display*

Sunblind L, Incomplete, E - Replace	<b>150,00</b>
-------------------------------------	---------------



Interior, Stain, Cleaning 75,00



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Centre console, Hole, Smart repair 110,64



Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Bump(s), Smart repair 110,64



Door panel R R, Scratch(es), E - Replace 114,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s), Acceptable 0,00

No pictures to display