


**FORD S Max: 1GEX469**

|                                    |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber:                        | <b>WF05XXGBWSEL09612</b> | Versionname: | <b>S-MAX Trend Style St/St</b> |
| First Registrationdate:            | <b>20/01/2014</b>        | Fiscalpower: | <b>DPF 115PK</b>               |
| Expertise Mileage:                 | <b>99495</b>             | Power Kw:    | <b>85</b>                      |
| Bodytype:                          | <b>MPV</b>               | Body color:  | <b>Dark Grey</b>               |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4823</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>5</b>                 |              |                                |
| Number head rests:                 | <b>5</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/60/16/99 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 3 mm</b> | Fr.R. | <b>Goodyear: 3 mm</b> |
|               | Re.L.                            | <b>Goodyear: 4 mm</b> | Re.R. | <b>Goodyear: 4 mm</b> |

**Assistance equipment**

|  |            |            |             |
|--|------------|------------|-------------|
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b>  |
| Total cost ex VAT                                  |            |            | <b>0,00</b> |
| Door R R, Scratch(es), Acceptable                  |            |            | <b>0,00</b> |
| <i>No pictures to display</i>                      |            |            |             |
| Wing F R, Scratch(es), Acceptable                  |            |            | <b>0,00</b> |
| <i>No pictures to display</i>                      |            |            |             |
| Tailgate, Scratch(es), Acceptable                  |            |            | <b>0,00</b> |
| <i>No pictures to display</i>                      |            |            |             |
| Roof, Scratch(es), Acceptable                      |            |            | <b>0,00</b> |
| <i>No pictures to display</i>                      |            |            |             |
| Roof pillar L, Bump(s) and scratch(es), Acceptable |            |            | <b>0,00</b> |
| <i>No pictures to display</i>                      |            |            |             |

*No pictures to display*