


MERCEDES B: 1GSI112

Vinnumber:	WDD2462121J255288	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	15/04/2014	Fiscalpower:	
Expertise Mileage:	71845	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	B5 19 DGN	Parking lot:	3109
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	589,16
-------------------	---------------

Door F L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Door frame R L, Bump(s) and scratch(es), It - Spot repair	115,56
---	---------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L; Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Stain, Cleaning 50,00

