


MERCEDES C: 1GRP576

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnnumber: | WDD2040021A949741 | Versionname: | C BER 220CDI BE Edition Avantgarde 163PK |
| First Registrationdate: | 9/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 175678 | Power Kw: | 120 |
| Bodytype: | | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3733 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | | Front parking sensors |
| GPS storage | HD | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/91 T LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 9 mm | Fr.R. | Continental: 9 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment










| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1911,33 |
|-------------------|----------------|

| | |
|---|-------------|
| Boot carpet, Waterinfiltration, P - Check | 0,00 |
|---|-------------|



| | |
|---|---------------|
| Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 220,18 |
|---|---------------|

| | | |
|--|--|--------|
|  | Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|  | Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|  | Bumper moulding R L, Deformed, P - Check | 0,00 |
|  | Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|  | Door F R, Bump(s), PDR - Knock out without painting | 111,00 |
|  | Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|  | Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|  | Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|  | Ignition key, Missing, E - Replace | 150,00 |
| No pictures to display | | |
| | Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

