



## CITRO?N GRAND C4 PICASSO: 1JJU491

Vinnnumber:	<b>VF73A9HC8EJ859631</b>	Versionname:	<b>1.6 E-HDI 115 MAN6 BUSINESS GPS</b>
First Registrationdate:	<b>6/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>191801</b>	Power Kw:	<b>85</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3226</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/60/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 0,5 mm</b>	Fr.R.	<b>Bridgestone: 0,5 mm</b>
	Re.L.	<b>Bridgestone: 0,5 mm</b>	Re.R.	<b>Bridgestone: 0,5 mm</b>

## Assistance equipment

Total cost ex VAT	153,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Electricity circuit, Not functioning (well), P - Check	0,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*